

Appendix A.
2017 Main Stem Erosion Repair Project
Feasibility Report, May 2016

Photo 1. *Site 1.* Existing trail along stream (photo looking upstream)



Photo 2. *Site 2.* Concrete and block on stream bank



Photo 3. Site 3. Eroding outer bank upstream of riprap (photo looking downstream)



Photo 4. Site 4. Undercut swale and downstream bank



Photo 5. *Site 5.* Moderate erosion on steep bank



Photo 6. *Site 6.* Steep eroding bank



Photo 7. *Site 7.* Stream bed debris & non-native materials



Photo 8. *Site 8.* Top of stream bank



Photo 9. *Site 9.* Undercut bank



Photo 10. *Site 10.* Protruding Culvert



Photo 11. *Site 11.* Protruding culvert



Photo 12. *Site 12.* Minor to moderate erosion on stream bank downstream of riprap



Photo 13. *Site 13.* Undercut bank



Photo 14. *Site 14.* Bare lower banks



Photo 15. *Site 15.* Brush in overflow channel

