

Photo 1. Site 1. Existing trail along stream (photo looking upstream)



Photo 2. Site 2. Concrete and block on stream bank



Photo 3. Site 3. Eroding outer bank upstream of riprap (photo looking downstream)



Photo 4. Site 4. Undercut swale and downstream bank



Photo 5. *Site 5.* Moderate erosion on steep bank



Photo 6. *Site 6.* Steep eroding bank



Photo 7. Site 7. Stream bed debris & non-native materials



Photo 8. Site 8. Top of stream bank



Photo 9. *Site 9.* Undercut bank



Photo 10. *Site 10.* Protruding Culvert



Photo 11. *Site 11.* Protruding culvert



Photo 12. *Site 12.* Minor to moderate erosion on stream bank downstream of riprap



Photo 13. Site 13. Undercut bank



Photo 14. Site 14. Bare lower banks



Photo 15. *Site 15.* Brush in overflow channel

